

## Turbosmart Product Fitment Guide

Our recommendations for Blow-off Valve selection are to be used a guide only. These recommendations are based on the engine being in or close to standard trim, and to ensure a straight forward installation. Due to space constraints larger BOV's, although better suited, have not been recommended for some models. However our largest BOV, say a Megasonic, will work successfully on a small engine, however its full potential will not be utilized. For a more accurate recommendation further details are required on the modifications to the vehicle. Please feel free to contact us to discuss an application further.

Make	Model	Year	FCD Model			BOV Adapter	Additional Information	Recommended Blow-off Valve							
			FCD 001	FCD 002	FCD 002S			BOV1	Vee Port	Plumb Back 25mm	Plumb Back 32mm	Plumb Back 38mm	Super-sonic	Dual Port	Mega-sonic
Audi	A3 1.8T	All		•		FG-ADA -HO25		•		•					
Audi	A4 1.8T	97+		•		FG-ADA -HO25		•	•	•				•	
Audi	TT 1.8T	00'+		•		FG-ADA -HO25		•	•	•					
Ford	Capri XR	All				FG-ADA -HO19	FCD not required, disconnect pressure switch	•	•						
Ford	TX3 Laser	All				FG-ADA -HO19	FCD not available	•	•					•	
Ford	TX5 Telstar	All		•		Supplied	Fabrication Required	•	•	•				•	•
Holden	VL Commodore	All				FG-ADA -WA38	Welding Required, block pressure relief valve		•			•		•	•
Mazda	323 Familia	All				FG-ADA -HO19	FCD not available	•	•						
Mazda	626, MX6	All		•		Supplied	Fabrication Required	•	•	•					
Mazda	RX7- S4 & S5	All		•		FG-ADA -HO19	Recommend custom fitment of larger BOV	•	•						
Mazda	RX7- S6 TT	All		•		FG-ADA -HO19	Requires two BOV's and adapter kits	•	•						
Mitsubishi	Cordia	All	•	•		Supplied	Welding Required	•	•		•				
Mitsubishi	Gallant VR4	All		•		FG-ADA -R32			•					•	•
Mitsubishi	Lancer GSR & EVO 1-7	All		•		FG-ADA -HO38			•			•		•	•
Mitsubishi	Starion	All	•	•		Supplied	Welding Required	•	•		•				
Nissan	Pulsar ET	All				Supplied	Welding Required	•	•		•				
Nissan	Pulsar - Sunny GTiR	All				FG-ADA -HO34			•					•	•
Nissan	180SX, Sylvia - CA18	Early		•		FG-ADA -SELB	Welding Required		•					•	•
Nissan	180SX, Sylvia - SR20	Late		•		FG-ADA -SELB	Welding Required, remove STD BOV LHS Guard		•					•	•
Nissan	200SX	All		•		FG-ADA -HO32			•					•	•
Nissan	300ZX - Single Turbo	Early				Supplied	Welding Required		•					•	•
Nissan	300ZX - Twin Turbo	Late			•	FG-ADA -HO32	Requires two BOV's and adapter kits	•	•					•	•
Nissan	Skyline GTS-T R32	All			•	FG-ADA -R32			•					•	•
Nissan	Skyline GTS-T R33 & R34	All				FG-ADA -R33			•					•	•
Nissan	Skyline GTR	All				FG-ADA -R32	Requires two BOV's and adapter kits		•					•	•
Saab	900 Turbo	86+				FG-ADA -HO25	FCD not required, BOV1 for low boost model only	•	•	•					
Saab	9000	86'-6/94'				FG-ADA -HO25	FCD not required, BOV1 for low boost model only	•	•	•					
Saab	9000	7/94'-98'	•	•		FG-ADA -HO25	BOV1 for low boost model only	•	•	•					
Saab	93	99'-01'	•	•		FG-ADA -HO25	BOV1 for low boost model only	•	•	•					
Subaru	Impreza WRX	94'-6/97'	•	•		FG-ADA -HO19		•	•						
Subaru	Impreza WRX & Sti	7/97'-7/98'	•	•		FG-ADA -HO32			•					•	•
Subaru	Impreza WRX & Sti	8/98'-10/00'	•	•		FG-ADA -MY99			•					•	•
Subaru	Impreza WRX & Sti	01'/02'		•		Model specific BOV	FCD must be connected at the MAP sensor								
Subaru	GT forester	98'/00'	•	•		FG-ADA -MY99			•					•	•
Subaru	GT forester	01'/02'	•	•		FG-ADA -FRST			•					•	•
Subaru	RS Liberty, Legacy	All	•	•		FG-ADA -HO19		•	•						
Subaru	Liberty B4 TT	All	•	•		FG-ADA -B4			•					•	•
Toyota	MR2 Turbo	All	•	•		FG-ADA -MR2			•					•	•
Toyota	Soarer 2.5I TT	All				FG-ADA -HO32	Disconnect standard BOV, do not remove		•					•	•
Toyota	Starlet GT	All	•	•		Supplied	Fabrication Required	•	•	•					
Toyota	Supra TT	All				FG-ADA -HO25	Recommend larger BOV cust. fit near throttle body		•						
VW	Beetle 1.8T	99+		•		FG-ADA -HO25		•		•					
VW	Golf 1.8T	00+		•		FG-ADA -HO25		•		•					
VW	Jetta 1.8T	00+		•		FG-ADA -HO25		•		•					
VW	Passat 1.8T	98+		•		FG-ADA -HO25		•		•					

### Notes:

- For the most complete and up to date information please refer to our website: [www.turbosmart.com.au](http://www.turbosmart.com.au) or contact us at [info@turbosmart.com.au](mailto:info@turbosmart.com.au)
- All BOV's come with a stainless steel adapter suited to welding in steel or stainless steel (FG-ADA -SS38)